

Report No: CAM-RP-2013-020 Rev N/C

Report Date: April 16, 2019

# NIAR Impact Testing Investigation Report For Hexcel 8552 IM7 Unidirectional Prepreg 190 gsm & 35%RC

NCAMP Test Report Number: CAM-RP-2013-020 Rev N/C

Report Date: April 16, 2019

#### **Testing Facility:**


National Institute for Aviation Research Wichita State University 1845 N. Fairmount Wichita, KS 67260-0093

#### Prepared by:

Soo Han Loo

#### **Edited by:**

Michelle Man, Katherine Carney




## Table of Contents

1.

2.

Report No: CAM-RP-2013-020 Rev N/C Report Date: April 16, 2019



Report No: CAM-RP-2013-020 Rev N/C

Report Date: April 16, 2019

### 1. Scope

Report No: CAM-RP-2013-020 Rev N/C Report Date: April 16, 2019

WICHITA ST

### 3. Analysis of setup

The impact setup was erroneous due to the use of a shorter extender where the tip of the impactor tup barely reached the top of the support base when the entire crosshead assembly rested on the brakes. Figure 1 illustrates the incorrect setup used where some of the impact energy was absorbed by the breaks during impact and resulted in a smaller damage area.

A correct impact setup, illustrated in Figure 2, would require utilization of a longer extender that would allow the impactor tup to go past the top of the support base for a complete energy transfer to the coupon before the crosshead assembly reaches the brakes.





Figure 1 – Incorrect Impact Setup for 2008 Qualification/Equivalency program



Report No: CAM-RP-2013-020 Rev N/C

Report Date: April 16, 2019






Figure 3



Report No: CAM-RP-2013-020 Rev N/C Report Date: April 16, 2019



Report No: CAM-RP-2013-020 Rev N/C Report Date: April 16, 2019




Figure 6 - Plots and C-Scan for 2013 Equivalency sample