



CACRC Depot Bonded Repair Investigation – Round Robin Testing

John Tomblin, PhD
Executive Director, NIAR

Lamia Salah
Sr. Research Engineer, NIAR



July 22nd, 2009

The Joint Advanced Materials and Structures Center of Excellence



FAA Sponsored Project Information



- Ø Principal Investigators & Researchers
 - Ø Dr. John Tomblin, Wichita State University
 - Ø Lamia Salah, Wichita State University
 - Ø Mike Borgman, Spirit Aerosystems

- Ø FAA Technical Monitor
 - Ø Curtis Davies, Lin Pham

- Ø Other FAA Personnel Involved
 - Ø Larry Ilcewicz, Peter Shyprykevich

- Ø Industry Participation
 - Ø Mike Borgman, Spirit Aerosystems

Wichita State University

JAMS



Wichita State University

July 22nd, 2009


The Joint Aoint

JAMS





- ∅ To investigate different variables on the performance of bonded repairs applied to sandwich structures
- ∅ To investigate the effectiveness of bonded OEM vs field repairs implemented at various OEM/ Operator depots
- ∅ To evaluate the static, fatigue and residual strength performance of OEM vs field repairs
- ∅ To evaluate the existing CACRC standards for composite repair implementation and technician training



Reference SAE ARP5089

JAMS

Previous Research



∅ Objective

Wichita State University

July 22nd, 2009




The Joint Advanced Materials and Structures Center of Excellence

6



OEM Prepreg Repair Method

- Ø Repair material:
- Ø T300/934 3K-70-PW prepreg with FM 377S adhesive
- Ø 0.25" overlap
- Ø No extra ply
- Ø 350°F cure




- Ø Picture Frame shear elements were sent to 4 different airline depots for repair
- Ø All depots were provided shear elements to repair using the OEM and the CACRC repair procedure
- Ø All shear elements were mechanically tested to failure

Wichita State University

JAMS



Previous Research- Repair after Contaminant Exposure




Wichita State University

Repair after Contaminant Exposure



- Ø Even after fully drying the repair joint, the original repair joint capability may not be restored
- Ø WA-0 specimens are specimens that were conditioned at 145°F 85%RH until moisture equilibrium then dried back to 0% moisture




Wichita State University

Repair after Contaminant Exposure

- ∅ WA-75 specimens are specimens that were conditioned at 145°F 85%RH until moisture equilibrium then dried back to 75% saturation

Ultimate Strength of WA-75 specimens tested at RTA



Wichita State University

JAMS





Repair after Contaminant Exposure



Wichita State University

July 22nd, 2009

The Joint Advanced Materials and Structures Center of Excellence


Previous Research – Lessons Learned



Adhesively Bonded Repairs are Process Dependent

- ∅ Repair Technician Training: technician training directly affects the quality (structural integrity of a bonded repair). Only properly/ recently trained technicians should perform bonded repairs
- ∅ Cure Cycle Deviation: an improper cure cycle will yield a deficient repair
- ∅ Contaminated Repair Surface: pre-bond moisture, contaminated repair surface will yield a substandard bonded repair


Bonded Repair Quality Assurance



Wichita State University

Proposed Research – Sandwich Coupon Configuration

- Ø Large beams, 12" x 48" with the repair tested in compression
- Ø 3-ply facesheets, 1/8" core cell size, 2" thick



- Ø Parent Material: T300/ 934 with FM 377S adhesive
- Ø Repair Materials: OEM repair using parent system (350°F cure)
 Field repair 1 using Hexcel M20 PW (250°F cure) - Prepreg
 Field repair 2 using Epocast 52A/B - Wet lay-up

Wichita State University

- Ø A 2.5" hole diameter will be used to simulate damage on all coupons
- Ø Detailed test matrix is outlined in figure 1 below
- Ø Airline depots: Northwest/ Delta, United (4 Depots)

Figure 1 : CACRC Round Robin Test Matrix

Repair Station	Coupon Configuration	Repair Type	Number of test Replicates Loading Mode		
			Compression Static RTA	Compression Static ETW	Compression RS ETW
OEM	Pristine/ Undamaged	N/A	6	6	6
OEM	2.5" hole	None		3	3
OEM	2.5" hole	2D-OEM		3	3
Field Station 1	2.5" hole	2D-R1		3	3
Field Station 1	2.5" hole	2D-R2		3	3
Field Station 2	2.5" hole	2D-R1		3	3
Field Station 2	2.5" hole	2D-R2		3	3
Field Station 3	2.5" hole	2D-R1		3	3
Field Station 3	2.5" hole	2D-R2		3	3
Field Station 4	2.5" hole	2D-R1		3	3
Field Station 4	2.5" hole	2D-R2		3	3
Total			6	36	36

JAMS



Wichita State University

July 22nd, 2009

The Joint Advanced Materials and S

18

Status/ Benefits to Aviation



- Ø NIAR will provide detailed Repair procedures to be reviewed by OEM (Airbus and Boeing)
- Ø Approved repair procedures will be supplied along with coupons to OEM/ field stations